SAFETY DATA SHEET

HHS4-C0037

Section 1. Identification : POWDURA® Hybrid Powder Coating **Product name** Driftwood **Product code** : HHS4-C0037 Other means of : Not available. identification **Product type** : Powder. Relevant identified uses of the substance or mixture and uses advised against Paint or paint related material. : THE SHERWIN-WILLIAMS COMPANY Manufacturer 101 W. Prospect Avenue Cleveland, OH 44115 National contact : Sherwin-Williams Canada Inc. 180 Brunel Road Mississauga, Ontario L4Z 1T5 Canada : US / Canada: (800) 424-9300 **Emergency telephone** number of the company Mexico: SETIQ 800-00-214-00 / 55-5559-1588 Available 24 hours and 365 days a year **Product Information** : US / Canada: 866-722-9710 **Telephone Number** Mexico: Not Available Transportation Emergency : US / Canada: (800) 424-9300 **Telephone Number** Mexico: SETIQ 800-00-214-00 / 55-5559-1588 Available 24 hours and 365 days a year

Section 2. Hazards identification

| Classification of the substance or mixture | : COMBUSTIBLE DUSTS SKIN CORROSION/IRRITATION - Category 2 SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2A CARCINOGENICITY - Category 2 SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Respiratory tract irritation) - Category 3 |
|--|--|
| | Percentage of the mixture consisting of ingredient(s) of unknown acute toxicity: 1.9% (oral), 1.9% (dermal), 1.9% (inhalation) |
| <u>GHS label elements</u> Hazard pictograms | |

Signal word

: Warning

| Date of issue/Da | ate of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version : 15 | 1/13 |
|---|-----------------|-------------|------------------------|------------------|--------------|------|
| HHS4-C0037 POWDURA® Hybrid Powder Coating | | | | SHW-85-NA-GHS-CA | | |
| | Driftwood | | | | | |

Section 2. Hazards identification

| Hazard statements | : Causes skin irritation. Causes serious eye irritation. May cause respiratory irritation. Suspected of causing cancer. May form combustible dust concentrations in air. |
|----------------------------------|---|
| Precautionary statements | |
| Prevention | : Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Wear protective gloves, protective clothing and eye or face protection. Use only outdoors or in a well-ventilated area. Avoid breathing dust or mist. Wash thoroughly after handling. |
| Response | : IF exposed or concerned: Get medical advice or attention. IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a POISON CENTER or doctor if you feel unwell. Take off contaminated clothing and wash it before reuse. IF ON SKIN: Wash with plenty of water. If skin irritation occurs: Get medical advice or attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice or attention. |
| Storage | : Store locked up. Store in a well-ventilated place. Keep container tightly closed. |
| Disposal | : Dispose of contents and container in accordance with all local, regional, national and international regulations. |
| Supplemental label elements | Keep container tightly closed. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Prevent dust accumulation. WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. FOR INDUSTRIAL USE ONLY. Adequate ventilation required when sanding or abrading the dried film. If Adequate ventilation cannot be provided wear an approved particulate respirator (NIOSH approved). Follow respirator manufacturer's directions for respirator use. DELAYED EFFECTS FROM LONG TERM OVEREXPOSURE. Abrading or sanding of the dry film may release Crystalline Silica which has been shown to cause lung damage and cancer under long term exposure. |
| | Please refer to the SDS for additional information. Keep out of reach of children. Do not transfer contents to other containers for storage. |
| Hazards not otherwise classified | : None known. |

Section 3. Composition/information on ingredients

| Substance/mixture | : Mixture |
|-------------------|------------------|
| Other means of | : Not available. |
| identification | |

CAS number/other identifiers

| Ingredient name | % by weight | CAS number |
|-------------------|-------------|------------|
| Calcium Carbonate | 23.78 | 1317-65-3 |
| Titanium Dioxide | 13.28 | 13463-67-7 |
| Barium Sulfate | 1.85 | 7727-43-7 |
| Carbon Black | 0.23 | 1333-86-4 |

Any concentration shown as a range is to protect confidentiality or is due to batch variation.

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified and hence require reporting in this section.

Occupational exposure limits, if available, are listed in Section 8.

Section 4. First aid measures

| Description of necessar | <u>y first aid measures</u> |
|-------------------------|---|
| Eye contact | Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 10 minutes. Get medical attention. |
| Inhalation | : Remove victim to fresh air and keep at rest in a position comfortable for breathing. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Get medical attention. If necessary, call a poison center or physician. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband. In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. |
| Skin contact | : Flush contaminated skin with plenty of water. Remove contaminated clothing and shoes. Continue to rinse for at least 10 minutes. Get medical attention. Wash clothing before reuse. Clean shoes thoroughly before reuse. |
| Ingestion | : Wash out mouth with water. Remove dentures if any. If material has been swallowed and the exposed person is conscious, give small quantities of water to drink. Stop if the exposed person feels sick as vomiting may be dangerous. Do not induce vomiting unless directed to do so by medical personnel. If vomiting occurs, the head should be kept low so that vomit does not enter the lungs. Get medical attention. Never give anything by mouth to an unconscious person. If unconscious, place in recovery position and get medical attention immediately. Maintain an open airway. Loosen tight clothing such as a collar, tie, belt or waistband. |

Most important symptoms/effects, acute and delayed

| moot important of mpton | lover bollo, addite and delayed |
|--------------------------|---|
| Potential acute health e | ffects |
| Eye contact | : Causes serious eye irritation. |
| Inhalation | : May cause respiratory irritation. |
| Skin contact | : Causes skin irritation. |
| Ingestion | : No known significant effects or critical hazards. |
| Over-exposure signs/sy | r <u>mptoms</u> |
| Eye contact | : Adverse symptoms may include the following: pain or irritation watering redness |
| Inhalation | : Adverse symptoms may include the following: respiratory tract irritation coughing |
| Skin contact | : Adverse symptoms may include the following: irritation redness |
| Ingestion | : No specific data. |
| Indication of immediate | nedical attention and special treatment needed, if necessary |
| Notes to physician | In case of inhalation of decomposition products in a fire, symptoms may be delayed. The exposed person may need to be kept under medical surveillance for 48 hours. |

Specific treatments : No specific treatment.

| Date of issue/Date | of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version : 15 | 3/13 |
|--------------------|---------------------------|--------------------|------------------------|-------------|------------------|------|
| HHS4-C0037 | POWDURA® Hyb Driftwood | rid Powder Coating | | | SHW-85-NA-GHS-CA | |

Section 4. First aid measures

Protection of first-aiders

: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation.

See toxicological information (Section 11)

Section 5. Fire-fighting measures

| Extinguishing media | |
|--|--|
| Suitable extinguishing media | : Use dry chemical powder. |
| Unsuitable extinguishing media | : Avoid high pressure media which could cause the formation of a potentially explosible dust-air mixture. |
| Specific hazards arising from the chemical | : May form explosible dust-air mixture if dispersed. |
| Hazardous thermal decomposition products | : Decomposition products may include the following materials: carbon dioxide carbon monoxide nitrogen oxides sulfur oxides halogenated compounds metal oxide/oxides |
| Special protective actions for fire-fighters | : Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool. |
| Special protective equipment for fire-fighters | : Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode. |

Section 6. Accidental release measures

| Personal precautions, protect | tiv | e equipment and emergency procedures |
|--------------------------------|-----|--|
| For non-emergency personnel | : | No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Shut off all ignition sources. No flares, smoking or flames in hazard area. Avoid breathing dust. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment. |
| For emergency responders | : | If specialized clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel". |
| Environmental precautions | : | Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air). |
| Methods and materials for co | nt | ainment and cleaning up |

Small spill: Move containers from spill area. Use spark-proof tools and explosion-proof equipment.
Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a
HEPA filter and place in a closed, labeled waste container. Place spilled material in a
designated, labeled waste container. Dispose of via a licensed waste disposal
contractor.

| Date of issue/Date | e of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version : 15 | 4/13 |
|--------------------|--------------------------------|----------------|------------------------|-------------|------------------|------|
| HHS4-C0037 | POWDURA® Hybrid F Driftwood | Powder Coating | | | SHW-85-NA-GHS-CA | ۱. |

Section 6. Accidental release measures

| Large spill | |
|-------------|--|
| | |

: Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Avoid dust generation. Do not dry sweep. Vacuum dust with equipment fitted with a HEPA filter and place in a closed, labeled waste container. Avoid creating dusty conditions and prevent wind dispersal. Dispose of via a licensed waste disposal contractor. Note: see Section 1 for emergency contact information and Section 13 for waste disposal.

Section 7. Handling and storage

Precautions for safe handling

| rioduatione for oure nanaling | |
|--|--|
| Protective measures | : Put on appropriate personal protective equipment (see Section 8). Avoid exposure - obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Do not get in eyes or on skin or clothing. Do not ingest. Avoid breathing dust. Avoid the creation of dust when handling and avoid all possible sources of ignition (spark or flame). Prevent dust accumulation. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Electrical equipment and lighting should be protected to appropriate standards to prevent dust coming into contact with hot surfaces, sparks or other ignition sources. Take precautionary measures against electrostatic discharges. To avoid fire or explosion, dissipate static electricity during transfer by grounding and bonding containers and equipment before transferring material. Empty containers retain product residue and can be hazardous. Do not reuse container. |
| Advice on general occupational hygiene | : Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. See also Section 8 for additional information on hygiene measures. |
| Conditions for safe storage, including any incompatibilities | : Store in accordance with local regulations. Store in a segregated and approved area. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see Section 10) and food and drink. Store locked up. Eliminate all ignition sources. Separate from oxidizing materials. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination. See Section 10 for incompatible materials before handling or use. |
| | |

Section 8. Exposure controls/personal protection

Control parameters

Occupational exposure limits (OSHA United States)

| Ingredient name | CAS # | Exposure limits OSHA PEL (United States, 5/2018). TWA: 5 mg/m³ 8 hours. Form: Respirable fraction TWA: 15 mg/m³ 8 hours. Form: Total dust NIOSH REL (United States, 10/2020). [calcium carbonate] TWA: 5 mg/m³ 10 hours. Form: Respirable fraction TWA: 10 mg/m³ 10 hours. Form: Total | | |
|---|---------------------------------|--|--|--|
| Calcium Carbonate | 1317-65-3 | | | |
| Titanium Dioxide | 13463-67-7 | OSHA PEL (United States, 5/2018). TWA: 15 mg/m ³ 8 hours. Form: Total dust ACGIH TLV (United States, 1/2023). TWA: 2.5 mg/m ³ 8 hours. Form: respirable | | |
| Date of issue/Date of revision | /18/2024 Date of previous issue | : 9/13/2023 Version : 15 5/13 | | |
| HS4-C0037 POWDURA® Hybrid Po Driftwood | ler Coating | SHW-85-NA-GHS-CA | | |

Section 8. Exposure controls/personal protection

| Barium Sulfate | 7727-43-7 | fraction, finescale particles ACGIH TLV (United States, 1/2023). |
|----------------|-----------|---|
| Danum Gunate | 1121-40-1 | TWA: 5 mg/m ³ 8 hours. Form: Inhalable |
| | | fraction |
| | | NIOSH REL (United States, 10/2020). |
| | | TWA: 5 mg/m ³ 10 hours. Form: Respirable |
| | | fraction |
| | | TWA: 10 mg/m ³ 10 hours. Form: Total |
| | | OSHA PEL (United States, 5/2018). |
| | | TWA: 5 mg/m ³ 8 hours. Form: Respirable fraction |
| | | TWA: 15 mg/m ³ 8 hours. Form: Total dust |
| Carbon Black | 1333-86-4 | NIOSH REL (United States, 10/2020). |
| | | TWA: 3.5 mg/m ³ 10 hours. |
| | | OSHA PEL (United States, 5/2018). |
| | | TWA: 3.5 mg/m ³ 8 hours. |
| | | ACGIH TLV (United States, 1/2023). |
| | | TWA: 3 mg/m ³ 8 hours. Form: Inhalable |
| | | fraction |

Occupational exposure limits (Canada)

| Ingredient name | CAS # | Exposure limits |
|-----------------|-----------|---|
| Carbon black | 1333-86-4 | CA British Columbia Provincial (Canada, 6/2022). TWA: 3 mg/m³ 8 hours. Form: Inhalable CA Ontario Provincial (Canada, 6/2019). TWA: 3 mg/m³ 8 hours. Form: Inhalable particulate matter. CA Quebec Provincial (Canada, 6/2022). TWAEV: 3 mg/m³ 8 hours. Form: inhalable dust CA Alberta Provincial (Canada, 6/2018). 8 hrs OEL: 3.5 mg/m³ 8 hours. CA Saskatchewan Provincial (Canada, 7/2013). STEL: 7 mg/m³ 15 minutes. TWA: 3.5 mg/m³ 8 hours. |

Occupational exposure limits (Mexico)

| Ingredient name | CAS # | Exposure limits |
|-----------------|-------|-----------------|
| None. | | |

Biological exposure indices (United States)

No exposure indices known.

Biological exposure indices (Canada)

No exposure indices known.

Biological exposure indices (Mexico)

No exposure indices known.

Date of previous issue

Section 8. Exposure controls/personal protection

| Appropriate engineering controls Environmental exposure controls | Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapor or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment. Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be necessary to reduce emissions to acceptable levels. |
|---|--|
| Individual protection measure | |
| | |
| Hygiene measures | : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location. |
| Eye/face protection | : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles. If operating conditions cause high dust concentrations to be produced, use dust goggles. |
| Skin protection | |
| Hand protection | : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated. |
| Body protection | : Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. |
| Other skin protection | : Appropriate footwear and any additional skin protection measures should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product. |
| Respiratory protection | : Based on the hazard and potential for exposure, select a respirator that meets the appropriate standard or certification. Respirators must be used according to a respiratory protection program to ensure proper fitting, training, and other important aspects of use. |
| | |

Section 9. Physical and chemical properties

The conditions of measurement of all properties are at standard temperature and pressure unless otherwise indicated.

Appearance

Driftwood

| Physical state | : Solid. | |
|---|---|------|
| Color | : Beige. | |
| Odor | : Not available. | |
| Odor threshold | : Not available. | |
| рН | : Not applicable. | |
| Melting point/freezing point | : Not available. | |
| Boiling point, initial boiling point, and boiling range | : Not available. | |
| Flash point | : Closed cup: Not applicable. | |
| Evaporation rate | : Not available. | |
| Date of issue/Date of revision | : 4/18/2024 Date of previous issue : 9/13/2023 Version : 15 | 7/13 |
| HHS4-C0037 POWDURA® Hyb | brid Powder Coating SHW-85-NA-GHS-CA | |

Section 9. Physical and chemical properties

| Flammability | : No | t available. |
|--|-------|---|
| Lower and upper explosion limit/flammability limit | : No | t applicable. |
| Vapor pressure | : No | t available. |
| Relative vapor density | : No | t applicable. |
| Relative density | : 1.6 | 33 |
| Solubility(ies) | : | |
| Media | | Result |
| cold water | | Not soluble |
| Partition coefficient: n- octanol/water | : No | t applicable. |
| Auto-ignition temperature | : No | t applicable. |
| Decomposition temperature | : No | t available. |
| Viscosity | : Ki | nematic (40°C (104°F)): >20.5 mm²/s (>20.5 cSt) |
| Molecular weight | : No | ot applicable. |
| Heat of combustion | : 0.1 | 38 kJ/g |

Section 10. Stability and reactivity

| | , , |
|------------------------------------|---|
| Reactivity | : No specific test data related to reactivity available for this product or its ingredients. |
| Chemical stability | : The product is stable. |
| Possibility of hazardous reactions | : Under normal conditions of storage and use, hazardous reactions will not occur. |
| Conditions to avoid | : Avoid the creation of dust when handling and avoid all possible sources of ignition (spark or flame). Take precautionary measures against electrostatic discharges. To avoid fire or explosion, dissipate static electricity during transfer by grounding and bonding containers and equipment before transferring material. Prevent dust accumulation. |
| Incompatible materials | : Reactive or incompatible with the following materials: oxidizing materials |
| Hazardous decomposition products | : Under normal conditions of storage and use, hazardous decomposition products should not be produced. |

Section 11. Toxicological information

Information on toxicological effects

| Acute toxicity | | | | |
|-------------------------|-----------|---------|--------------|----------|
| Product/ingredient name | Result | Species | Dose | Exposure |
| Carbon Black | LD50 Oral | Rat | >15400 mg/kg | - |

Irritation/Corrosion

| Product/ingredient name | Result | Species | Score | Exposure | Observation |
|-------------------------|----------------------|---------|-------|--------------|-------------|
| Titanium Dioxide | Skin - Mild irritant | Human | - | 72 hours 300 | - |
| | | | | ug l | |

| Date of issue/Date | of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version : 15 | 8/13 |
|--------------------|---------------------------------|--------------------------------------|------------------------|-------------|------------------|------|
| HHS4-C0037 | POWDURA® Hybrid Po Driftwood | VDURA® Hybrid Powder Coating wood | | | SHW-85-NA-GHS-CA | |
| | | | | | | |

Section 11. Toxicological information

Sensitization

Not available.

Mutagenicity

Not available.

Carcinogenicity

Not available.

Classification

| Product/ingredient name | OSHA | IARC | NTP |
|----------------------------------|------|----------|-----|
| Titanium Dioxide Carbon Black | - | 2B 2B | - |

Reproductive toxicity

Not available.

Teratogenicity

Not available.

Specific target organ toxicity (single exposure)

| Name | | Route of exposure | Target organs |
|-------------------|------------|----------------------|------------------------------|
| Calcium Carbonate | Category 3 | | Respiratory tract irritation |

Specific target organ toxicity (repeated exposure)

Not available.

Aspiration hazard

Not available.

| Information on the likely routes of exposure | : | Not available. |
|--|-----|--|
| Potential acute health effect | cts | |
| Eye contact | : | Causes serious eye irritation. |
| Inhalation | : | May cause respiratory irritation. |
| Skin contact | : | Causes skin irritation. |
| Ingestion | : | No known significant effects or critical hazards. |
| <u>Symptoms related to the pl</u> Eye contact | | sical, chemical and toxicological characteristics Adverse symptoms may include the following: pain or irritation |
| | | watering redness |
| Inhalation | : | Adverse symptoms may include the following: respiratory tract irritation coughing |
| Skin contact | : | Adverse symptoms may include the following: irritation redness |
| Ingestion | : | No specific data. |

| Date of issue/Date | of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version : 15 | 9/13 |
|--------------------|--------------------------------|---------------|------------------------|-------------|------------------|------|
| HHS4-C0037 | POWDURA® Hybrid P Driftwood | owder Coating | | | SHW-85-NA-GHS-CA | |

Section 11. Toxicological information

| Delayed and immediate ef | fects and also chronic effects from short and long term exposure |
|------------------------------|--|
| <u>Short term exposure</u> | |
| Potential immediate | : Not available. |
| effects | |
| Potential delayed effects | : Not available. |
| <u>Long term exposure</u> | |
| Potential immediate | : Not available. |
| effects | |
| Potential delayed effects | : Not available. |
| Potential chronic health e | ifects |
| Not available. | |
| General | : Repeated or prolonged inhalation of dust may lead to chronic respiratory irritation. |
| Carcinogenicity | : Suspected of causing cancer. Risk of cancer depends on duration and level of exposure. |
| Mutagenicity | : No known significant effects or critical hazards. |
| Teratogenicity | : No known significant effects or critical hazards. |
| Developmental effects | : No known significant effects or critical hazards. |
| Fertility effects | : No known significant effects or critical hazards. |
| | |
| Numerical measures of to | <u>xicity</u> |

Acute toxicity estimates Not available.

Section 12. Ecological information

| <u>Toxicity</u> | | | |
|------------------------------------|--|---|----------------------------------|
| Product/ingredient name | Result | Species | Exposure |
| Titanium Dioxide Barium Sulfate | Acute LC50 >1000000 μg/l Marine water Acute EC50 634 mg/l Fresh water Acute EC50 32 mg/l Fresh water | Fish - <i>Fundulus heteroclitus</i> Crustaceans - <i>Cypris subglobosa</i> Daphnia - <i>Daphnia magna</i> | 96 hours 48 hours 48 hours |

Persistence and degradability

Not available.

Bioaccumulative potential

Not available.

Mobility in soil

Soil/water partition : Not available. coefficient (Koc)

Other adverse effects : No known significant effects or critical hazards.

| Date of issue/Date | of revision | : 4/18/2024 | Date of previous issue | : 9/13/2023 | Version | :15 | 10/13 |
|--------------------|--------------------------------|---------------|------------------------|-------------|---------|-----------|-------|
| HHS4-C0037 | POWDURA® Hybrid P Driftwood | owder Coating | | | SHW-85- | NA-GHS-CA | |

Section 13. Disposal considerations

Disposal methods

: The generation of waste should be avoided or minimized wherever possible. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Section 14. Transport information

| | DOT Classification | TDG Classification | Mexico Classification | ΙΑΤΑ | IMDG |
|---|-----------------------|-----------------------|--------------------------|----------------|----------------|
| UN number | Not regulated. | Not regulated. | Not regulated. | Not regulated. | Not regulated. |
| UN proper shipping name | - | - | - | - | - |
| Transport hazard class(es) | - | - | - | - | - |
| Packing group | - | - | - | - | - |
| Environmental hazards | No. | No. | No. | No. | No. |
| Additional information | - | - | - | - | - |
| Special precautions for user : Multi-modal shipping descriptions are provided for informational purposes and do not consider container sizes. The presence of a shipping description for a particular mode of transport (sea, air, etc.), does not indicate that the product is packaged suitably for that mode of transport. All packaging must be reviewed for suitability prior to shipment, and compliance with the applicable regulations is the sole responsibility of the person offering the product for transport. People loading and unloading dangerous goods must be trained on all of the risks deriving from the substances and on all actions in case of emergency situations. | | | | | |
| Transport in bulk ac to IMO instruments | | | , | | |

Proper shipping name : Not a

: Not available.

Section 15. Regulatory information

International regulations

Montreal Protocol

Not listed.

Stockholm Convention on Persistent Organic Pollutants Not listed.

International lists : Australia inventory (AIIC): Not determined. China inventory (IECSC): Not determined. Japan inventory (CSCL): Not determined. Japan inventory (ISHL): Not determined. Korea inventory (KECI): Not determined. New Zealand Inventory of Chemicals (NZIoC): Not determined. Philippines inventory (PICCS): Not determined. Taiwan Chemical Substances Inventory (TCSI): Not determined. Thailand inventory: Not determined. Turkey inventory: Not determined. Vietnam inventory: Not determined.

Section 16. Other information

Hazardous Material Information System (U.S.A.)



The customer is responsible for determining the PPE code for this material. For more information on HMIS® Personal Protective Equipment (PPE) codes, consult the HMIS® Implementation Manual.

Caution: HMIS® ratings are based on a 0-4 rating scale, with 0 representing minimal hazards or risks, and 4 representing significant hazards or risks. Although HMIS® ratings and the associated label are not required on SDSs or products leaving a facility under 29 CFR 1910.1200, the preparer may choose to provide them. HMIS® ratings are to be used with a fully implemented HMIS® program. HMIS® is a registered trademark and service mark of the American Coatings Association, Inc.

Procedure used to derive the classification

| | Classification | | | | |
|--|---|--|--|--|--|
| COMBUSTIBLE DUSTS SKIN CORROSION/IRRIT/ SERIOUS EYE DAMAGE/ CARCINOGENICITY - Cat SPECIFIC TARGET ORG/ irritation) - Category 3 | On basis of test data Calculation method Calculation method Calculation method Calculation method | | | | |
| History | | | | | |
| Date of printing | : 4/18/2024 | | | | |
| Date of issue/Date of revision | : 4/18/2024 | | | | |
| Date of previous issue | te of previous issue : 9/13/2023 | | | | |
| Version | : 15 | | | | |

12/13

| Date of issue/Date | of revision | : 4/18/2024 | Date of previous issue | :9/13/2023 | Version | :15 |
|--------------------|-------------------|---------------|------------------------|------------|---------|-------------|
| HHS4-C0037 | POWDURA® Hybrid P | owder Coating | | | SHW-8 | 5-NA-GHS-CA |
| | Driftwood | | | | | |

Section 16. Other information

| Key to abbreviations | : ATE = Acute Toxicity Estimate |
|----------------------|--|
| | BCF = Bioconcentration Factor |
| | GHS = Globally Harmonized System of Classification and Labelling of Chemicals |
| | IATA = International Air Transport Association |
| | IBC = Intermediate Bulk Container |
| | IMDG = International Maritime Dangerous Goods |
| | LogPow = logarithm of the octanol/water partition coefficient |
| | MARPOL = International Convention for the Prevention of Pollution From Ships, 1973 |
| | as modified by the Protocol of 1978. ("Marpol" = marine pollution) |
| | N/A = Not available |
| | SGG = Segregation Group |
| | UN = United Nations |
| | |

Indicates information that has changed from previously issued version.

Notice to reader

It is recommended that each customer or recipient of this Safety Data Sheet (SDS) study it carefully and consult resources, as necessary or appropriate, to become aware of and understand the data contained in this SDS and any hazards associated with the product. This information is provided in good faith and believed to be accurate as of the effective date herein. However, no warranty, express or implied, is given. The information presented here applies only to the product as shipped. The addition of any material can change the composition, hazards and risks of the product. Products shall not be repackaged, modified, or tinted except as specifically instructed by the manufacturer, including but not limited to the incorporation of products not specified by the manufacturer, or the use or addition of products in proportions not specified by the manufacturer. Regulatory requirements are subject to change and may differ between various locations and jurisdictions. The customer/buyer/user is responsible to ensure that his activities comply with all country, federal, state, provincial or local laws. The conditions for use of the product are not under the control of the manufacturer; the customer/buyer/user is responsible to determine the conditions necessary for the safe use of this product. The customer/buyer/user should not use the product for any purpose other than the purpose shown in the applicable section of this SDS without first referring to the supplier and obtaining written handling instructions. Due to the proliferation of sources for information such as manufacturer-specific SDS, the manufacturer cannot be responsible for SDSs obtained from any other source.