PARRA®

ULTRA Pearl Kitchen & Bath 8210 Interior 100% Acrylic Latex Paint

Pearl Finish

Product Description

PARA Ultra Pearl Kitchen & Bath Paint is a top quality interior paint formulated with excellent adhesion and flexibility of 100% acrylic latex, provide the highest level of performance. It's smooth and even finish is easy to apply with excellent flow and leveling. This high-hiding, excellent coverage, scrubbable and washable paint has exceptional stain resistance. Formulated to resist mildew from forming on the surface which is ideal for kitchens, baths and spa-like retreat. May also be used on doors, trim and walls throughout your home.

Advantages

- A water-based product, which makes tools cleaning easier.
- A 100% acrylic product for excellent adhesion and flexibility.
- Paint and Primer in One.
- Exceptional performance in terms of washability, durability and stain resistance.
- Formulated to resist mildew from forming on the surface.
- Dries rapidly with a low odour. Non-yellowing.
- Product that complies with the Canadian environmental standards in relation to volatile organic compounds (VOC).

Projects

Environment

Interior.

Use

New or maintenance work. Walls, doors and trim used for any room of the house: kitchen and bathroom, living and dining room, master and children's bedroom, hall and play room.

Surfaces

All surfaces painted with water or solvent-based products. It is essential to prepare the surface prior to applying the product.

Note

Surface imperfections may be more noticeable with this product. Not suitable for floors. Do not mix with other paints or solvents.

Pre-mixed colors, tinting bases and sizes

Consult your Para retailer.

Characteristics

Physical Form Liquid

Quality First Choice

Transparency Solid

Gloss Level Pearl

Gloss Percentage

Gloss at 60°: 20 to 25% Gloss at 85°: 55 to 65%

Composition

- Diluent: water
- Binder: 100% acrylic resin
- Pigments: titanium dioxide

Spreading Rate

3.7 L: 450 to 500 ft² (41 to 46 m²) @ 1 - 1.2 mils DFT depending on surface porosity.

Drying Time

- Tack free: 4 to 6 hours
- Recoating: 6 to 8 hours

Density*

 1.28 ± 0.02 g/mL

Solids in Volume* $36 \pm 1\%$

Flash Point* Not applicable

Inflammability Nonflammable

PARA guarantees the quality of its products. They are in conformity with the description provided in the technical data sheets and on the labels for which they are intended, as indicated by the company. However, since the manufacturer has no control over the circumstances, the methods and the conditions appropriate to their intended uses, this guarantee applies only to the high quality of PARA products.

TDS_8210 (Aug 3, 2017)

Surface Preparation

Surface preparation is of the utmost importance. The majority of problems attributable to coatings are caused by inadequate surface preparation. Surfaces must be clean, solid, free from dust, dirt, oil, soot, wax, mildew, chalking, patina or flaking, etc. In order to prepare surfaces adequately, follow the preparation steps as described below:

- Clean surface with the appropriate product. TSP cleaner is the most common cleaner used for surfaces to be painted. To remove mildew, wash with a solution of household bleach (1 part household bleach for 3 parts of water). If wood exudes resin, scrape the excess and clean surface with alcohol or paint thinner.
- Strip or scrape all loose paint.
- Sand surfaces using No. 100-180 grit sandpaper. Vacuum sanding residues. (Precautionary measures: operations such as dry sanding or paint film burning may generate dust and harmful fumes. If possible, use the wet sanding method. If exposure cannot be avoided by means of local ventilation, wear a breathing mask).
- Repair holes and cracks with a paste filler suitable to surface being repaired. Some fillers, such as joint cement, are not suitable for previously painted surfaces as they may affect adhesion and cause blistering.
- On bare wood, seal knots with shellac.
- Apply the primer appropriate to the surface you want to paint. Using the same company brand primer and finishing products will assure better adhesion. Before applying the primer, cover or mask surfaces that you do not wish to paint. Consult your retailer for additional information. NOTE: (This finish is designed to be used as an All-in-One Paint & Primer product and a primer is generally not needed. However, performance, coverage, uniformity and application properties can be enhanced by using a primer). Listed below are recommended primers products.
 - Bare gypsum (drywall), new and dry plaster water-based primer-sealer.
 - Bare wood: water-based primer or solvent-based primer.
 - Cedar and redwood: solvent-based primer.
 - Dry aged plaster: solvent-based primer.
 - Previously varnished surfaces: solvent-based primer.
 - Smooth Masonry, Brick or Concrete: water-based primer
 - Porous surfaces such as Concrete Cinder Blocks: Latex Block Filler
 - No primer is required on previously painted latex in good condition

Application

- This is a ready-to-use product and should not be diluted.
- Thoroughly stir the product before application.
- Condition the tools with water before using them.
- Apply generously, leaving no bare spots or excesses of paint. Respect product spread rate. When painting, mark out a section of about 2 x 4 feet with a roller by drawing a "W". Without lifting the roller from the surface, fill in the "W". Smooth out the unpainted portion in the direction of the painted portion.
- Respect the drying time between coats. Low temperatures or high humidity may affect the drying time. Applying two finishing coats will provide better durability and appearance.
- If using, remove the masking tape after each coat to avoid lifting off paint when work is completed.
- To obtain more information on application methods, visit the website at www.para.com

Recommendations

Application Conditions

- Temperature: 15°C to 25°C (60°F to 77°F)
- Relative humidity: 30 50%
- Provide adequate ventilation during application and drying time. Avoid draughts.

Tools

- Paintbrush: nylon polyester bristles
- Roller: 10 13 mm
- Spray gun tip: 0.017 0.019 in

Cleaning of the Tools

Remove excess product and clean tools with lukewarm water and soap.

Surface Maintenance

Allow to dry 30 days before washing, using a non-abrasive cleaning solution and a soft rag.

Storage and Transportation

Keep product in a cool, dry and wellventilated area. Avoid freezing. Pot-life for this product is approximately 5 years.

Disposal

Contact your municipality to dispose of leftover products.

Safety Measures

See material safety data sheet for complete health and safety info. May cause eye irritation. Avoid contact with eyes. Keep out of reach of children. Use under well ventilated conditions.

FIRST AID TREATMENT: Contains small amounts of non-ionic surfactants. In case of contact with eyes, flush well with running water. If swallowed, call poison centre or physician immediately.